
OWM_SLEEP (E)
1Wire high after OWT_MIN_RESET
Falling edge
OWM_SLEEP (ET)
Falling edge
1Wire low after OWT_MIN_RESET
OWM_CHK_RESET (Er)
Rising edge
OWM_RESET (T)
after OWT_RESET_PRESENCE
set 1Wire low
(E) pin change interrupt enabled (falling edge)
(Er) pin change interrupt enabled (rising edge)
(T) timer interrupt enabled
(ET) timer and pin change interrupt enabled (falling edge)
OWM_PRESENCE (T)
OWM_READ_COMMAND (E)
after OWT_RESET_PRESENCE
set 1Wire high
8 times
Falling edge
after OWT_READLINE
read 1Wire line
OWM_READ_COMMAND (T)
OWM_READ_SCRATCHPAD
OWM_WRITE_SCRATCHPAD
OWM_MATCH_ROM
OWM_SEARCH_ROM